



8/4

14/16

14/16

14/16

opaž v kapu nad špirovci predvidoma ostane,  
 pri izvedbi preveriti ustreznost,  
 pri izvedbi preveriti stabilnost slepih špirovcev.

16/16

16/16

16/16

